


2016 CRACK SEALING OVERVIEW

- #1 Copperfield area - 27,000 lf
- #2 Garden Lane area - 12,000 lf
- #3 E. Van Buren Street - 10,000 lf
- #4 E. Denver area - 10,000 lf
- #5 E. Saint Joseph St - 26,000 lf
- #6 E. Indiana St - 14,000 lf
- #7 E. Fairmont Blvd - 36,000 lf
- #8 W. Blvd - 28,000 lf
- #9 Belmont area - 25,000 lf
- #10 Ridgewood area - 24,000 lf
- #11 Dunham area - 5,000 lf
- #12 Severson area - 13,000 lf

Total = 230,000



#1 - COPPERFIELD DR

ESTIMATED CRACK SEALING = 27,000'




#2 - GARDEN LANE AREA

ESTIMATED CRACK SEALING = 12,000'



#3 - E VAN BUREN

ESTIMATED CRACK SEALING = 10,000'



#4 - DENVER

ESTIMATED CRACK SEALING = 10,000'



#5 - E SAINT JOSEPH STREET

ESTIMATED CRACK SEALING = 26,000'



#6 - INDIANA

ESTIMATED CRACK SEALING = 14,000'



#7 - E. FAIRMONT BLVD

ESTIMATED CRACK SEALING = 36,000'




#8 - WEST BOULEVARD

ESTIMATED CRACK SEALING = 28,000'




#9 - BELMONT

ESTIMATED CRACK SEALING = 25,000'



#10 - RIDGEWOOD AREA

ESTIMATED CRACK SEALING = 24,000'



#11 - DUNHAM

ESTIMATED CRACK SEALING = 5,000'

